## Oil Field Environmental Incident Summary

**Responsible Party:** XTO ENERGY INC. **Well Operator:** XTO ENERGY INC.

Well Name: WILLEY 31X-3

Field Name: WEST CAPA Well File #: 21376

Date Incident:5/23/2016Time Incident:11:00Facility ID Number:County:WILLIAMSTwp:154Rng:97Sec:3Qtr:

Location Description:

Submitted By: JORDAN WOLF Received By:

Contact Person: JORDAN WOLF

P.O Box 6506 321 22ND AVE E WILLISTON, ND 58801

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 4 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 7/29/2016 Clean Up Concluded: 6/3/2016

Risk Evaluation:

produced water, non-sour well

Areal Extent:

## Potential Environmental Impacts:

None- spill was contained in and near edge of treater containment. No environment receptors near the impacted area.

## Action Taken or Planned:

All the wells were shut in. The production lines were isolated and tested to find the leaky connection. Free liquids are being removed and will be hauled to an approved SWD. The impacted material outside containment will be removed and hauled to an approved waste disposal facility.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

## **Updates**

Date: 5/25/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location according to the report. NDIC retains oversight.